
REJUVENATION

Specifications:



IMPORTANT INSTALLATION INFORMATION

- USE TEFLON TAPE OR PIPE SEALANT FOR THREADED CONNECTIONS
- DO NOT USE PLUMBER'S PUTTY ON ANY OF THE BRASS COMPONENTS This will cause the finish to tarnish and void the warranty. A non-corrosive Alkoxy Silicone is recommended.
- DURING SWEATING OF LINES DO NOT OVERHEAT CASTING Overheating may cause damage to internal mechanism
- COPPER ADAPTORS MAY BE REQUIRED TO COMPLETE YOUR INSTALLATION

For technical support, please call 718-257-2800

REJUVENATION

RJ-23-7.4G-WSP

Parts Breakdown – Hand Spray:	ITEN
(12) (1) (15) (17) (19) (18) (14) $($	
	1
5 	1 2 2
(26)	
25	:

ITEM NO.	PART NUMBER	QTY.
1	MSA6-SPRY-BODY	1
2	MSA6-SPRY-FACE-PLT	1
3	MSA6-SPRY-HEAD	1
4	MSA6-SPRAY	1
5	MSA4-HOSE-NUT	1
6	MSA6-INNR-NPPL	1
7	MSA4-INNR-NUT	1
8	A\$568 - 011	1
9	A\$568 - 015	1
10	A\$568 - 012	1
11	MSA4-LVR-NUT	1
12	MSA4-PIN	1
13	MSA4-GSKT	2
14	MSA4-SPRNG	1
15	MSA4-SPRNG-CAP	1
16	9X4.2X.75-STL-WSHR	1
17	MSA4-PLNGR	1
18	MSA4-PLNGR-CAP	1
19	A\$568 - 010	1
20	A\$568 - 020	1
21	MSA4-HOSE-GSKT	1
22	MSA4-HOSE-RETAIN-RING	1
23	MSA4-HOSE-WSHR	1
24	H-BS24-OUTR	1
25	H-BS24-LOCK-NUT	1
26	H-BS24-INNR	1
27	A\$568 - 125	1

IMPORTANT INSTALLATION INFORMATION

- USE TEFLON TAPE OR PIPE SEALANT FOR THREADED CONNECTIONS
- DO NOT USE PLUMBER'S PUTTY ON ANY OF THE BRASS COMPONENTS This will cause the finish to tarnish and void the warranty. A non-corrosive Alkoxy Silicone is recommended.
- DURING SWEATING OF LINES DO NOT OVERHEAT CASTING Overheating may cause damage to internal mechanism
- COPPER ADAPTORS MAY BE REQUIRED TO COMPLETE YOUR INSTALLATION

For technical support, please call 718-257-2800